INTERAGENCY SEAT OPERATION PROCEDURES HANDBOOK 2006 Summary of Changes

- Changed BLM National SEAT Web Site address to (throughout the document): http://www.aviation.blm.gov/airops.htm
- Under Makes and Models: Added web address for additional aircraft information and pictures for SEAT makes and models: http://www.aviationfirefighting.com/
- Corrected the Dromader (Piston / Turbine) overall length specification on chart. (*Page: 13*)
- Change Bi-Annual to "Tri-Annual SEAT Re-Fresher" Requirements: Added the numerical course designator for the re-fresher. RT-273 (*Document Wide*)
- **Under Contract Authority:** Add new language about the Project Inspector designation. (*Page 38-39*)
- Under Required Agency Documentation: Added new language requiring the SEAT Manager to use only the forms with the current year displayed on the bottom of the form. (*Page 48*)
- New Form Format for: SEAT Tanker Log / Cost Summary Sheet (SEAT-006 2006) (Page 63)
- New Form Format for: SEAT Cost Summary (Supplemental SEAT-006 2006) (*Page 64*)